

PSE Complaint No. 3

Requestor:

Erika Hunter
Damage Prevention Program Manager
Puget Sound Energy
P.O. Box 97034, EST-11W
Bellevue, WA 98009-9734
Erika.Hunter@pse.com
425-456-2854

Alleged violator:

Ben Tanielian
Employee: Max
TT & E, LLC
26910 92nd Ave NW
Stanwood, WA 98292

Date: 08/08/2016

Location: 13408 NE 129th Street, Lot #3, Kirkland WA


Violation: Digging without locates; RCW 19.122.30 (2) and (5)

Summary:

On August 8th 2016 PSE's Damage Prevention Field Rep, Roger Arrington, came across a TT & E LLC crew excavating in Kirkland WA at 13408 NE 129th Street, Lot #3. Roger checked for a valid ticket on the ITIC site www.managetickets.com and found that a TT& E employee, Max, was digging without calling for locates which is a violation of RCW 19.122.30 (2) and (5). Roger stopped the work, asked them to call the owner Ben, and told them not to dig until they called for and received locates.

On 08/08/2016 www.managetickets.com does show that a ticket, 16250569, was called in, at 1:04 pm, for the same jobsite with a work to begin date on 08/11/2016. The search was conducted for a ticket from 06/01/2016. This is the only ticket for TT & E LLC, for this address within that time period.

Roger documented the jobsite with photos that he took at 1:12 pm that day.



The screenshot displays a photo viewer interface. On the left, a photograph shows a red pickup truck with 'TTE' branding parked on a paved area. In the background, a yellow Hyundai excavator is visible. The photo viewer includes a toolbar at the bottom with navigation icons. Overlaid on the right is the 'IMG_0395.JPG Properties' dialog box, which is currently on the 'Details' tab. The dialog box contains a table of metadata for the image.

Property	Value
Description	
Title	
Subject	
Rating	☆☆☆☆
Tags	
Comments	
Origin	
Authors	
Date taken	8/8/2016 1:12 PM
Program name	9.3.2
Date acquired	
Copyright	
Image	
Image ID	
Dimensions	640 x 480
Width	640 pixels
Height	480 pixels
Horizontal resolution	72 dpi
Vertical resolution	72 dpi

Remove Properties and Personal Information

OK Cancel Apply

[Login](#) [Choose State](#) [Email Ticket](#) [Return to Search](#)

Washington One Call

Ticket No: 16250569 **2 FULL BUSINESS DAYS**
Original Call Date: 08/08/16 01:04 pm
Work to Begin Date: 08/11/16 12:00 am

TICKET ACTIONS

CALLER INFORMATION

Company Name: TT AND E LLC
Contact Name: BEN TANELIAN
Alt. Contact:
Phone: 425-754-7731
Phone:
Fax Phone:
Caller Address: PMB 101 3405 172ND ST ARLINGTON,WA 98223
Email Address: btanielian@gmail.com

DIG SITE INFORMATION

Type of Work: INSTALL FOUNDATION
Work Being Done For: HARBOUR HOMES

DIG SITE LOCATION

State: WA **County:** KING
Place: KIRKLAND **Address:** 13408
Street: NE 129TH ST
Intersecting Street: 136TH AVE NE
Location of Work: EXCAVATION SITE IS ON THE N SIDE OF THE ROAD. ADD IS APX 1000FT W FROM THE ABV INTR
MARK THE ENTIRE LOT AT THE ABV ADD
MARK AREAS MARKED IN WHITE
Remarks: BEST INFORMATION AVAILABLE
Map Coord NW Lat: 47.7166137 **Lon:** -122.1627364















TT&E. Address 13408 ne129 st

Arrington, Roger

You forwarded this message on 8/9/2016 1:17 PM.

Sent: Tue 8/9/2016 1:10 PM

To: Hunter, Erika

Message

IMG_0401.JPG (193 KB)	ATT00001.txt (230 B)	IMG_0400.JPG (157 KB)	ATT00002.txt (230 B)
IMG_0399.JPG (183 KB)	ATT00003.txt (230 B)	IMG_0398.JPG (170 KB)	ATT00004.txt (230 B)
IMG_0397.JPG (147 KB)	ATT00005.txt (230 B)	IMG_0396.JPG (126 KB)	ATT00006.txt (230 B)

Stopped on 8/8. No locates called

