ANTENNA AND TOWER ROUTINE INSPECTION

SITE NAME: Bellingham, WA.

SITE LOCATION: Central Office

SITE CLLI: BHLMWA01

DATE: 08/21/2018

INSPECTED BY: Larry Hogue/Rick Harris

Antenna and Tower Routine Inspection

1. Tower - Structure

	Inspect	OK	Dev.	NA
	Nuts and bolts for tightness.	_X_		
	Guy wire for proper tension			_x_
	Guy wire condition – Fraying, broken, etc			_x_
	Condition of concrete footings. (Cracking, settling & etc.)	_x_		
	Paint - Fading, peeling, etc.	_X_		
	Ladders & steps - safe and secure	_X_		
	Safety climbing device - safe and secure		_X_	
	Grounding and lightning protection - satisfactory	_X_		
	Structural units – damaged or missing	_X_		
	Tower lighting - operating correctly			_x_
2.	Antenna & Waveguide			
	Waveguide - properly supported	_X_		
	Flex waveguide - good condition	_X_		
	Connector Heads - sealed properly	_X_		
	Flex waveguide jumpers – correctly placed	_X_		
	Antenna nut and bolts – tight and secure	_X_		
	Antenna mount – tight and secure	_X_		
	Azimuth and stiff arms – tight and secure	_X_		
	Antenna covers – good condition	_X_		
	Waveguide hatch – sealed and grounded	_x_		

Note: If any Deviations are found explain in detail in notes section.

Antenna and Tower routine inspection

3. Air Pressure

	Inspect	OK	DEV.	NA
	Dehydrator Manifold – installed properly	_X_		
	Pressure – correct for antenna and system	_x_		
	Waveguide system – tight – no air leaks	_X_		
	Pressure alarm switches – installed and functioning	_x_		
	Horn antennas – water traps and proper pressure			_x_
4.	Environment			
	Path obstructions - Trees, shrubs, weeds and buildings.	_X_		
	Security - Gates, fences and doors secure.	_X_		
	General appearance – Weeds, Trash & etc.	_x_		
5.	Deviations notes, exceptions and recommendations			
	Explain in detail:			