ANTENNA AND TOWER ROUTINE INSPECTION

SITE NAME - Mt. Constitution North Tower

SITE LOCATION - Orcas Island

SITE CLLI - MTCSWAQA

DATE - 11/06/2019

INSPECTED BY - Hogue/Harris

Antenna and Tower Routine Inspection

1. Tower - Structure **NOTE** This is leased space. All inspection items as they relate to the structure are in close proximity to our antenna(s).

	Inspect	OK	Dev.	NA
	Nuts and bolts for tightness.	_X_	_	17
	Guy wire for proper tension	Not	Inspected	
	Guy wire condition - Fraying, broken, etc	e e e	_	Not Inspected
	Condition of concrete footings. (Cracking, settling & etc.)	1	_	Not Inspected
	Paint - Fading, peeling, etc.	_	(Not Inspected
	Ladders & steps - safe and secure	_	_X_	-
	Safety climbing device - safe and secure	_X_		
	Grounding and lightning protection - satisfactory	_X_		
	Structural units - damaged or missing	_X_		
	Tower lighting - operating correctly			Not Inspected
2.	Antenna & Waveguide			
	Waveguide - properly supported	_X_		
	Flex waveguide - good condition			_X_
	Connector Heads - sealed properly	_X_		
	Flex waveguide jumpers – correctly placed			_X_
	Antenna nut and bolts - tight and secure	_X_		
	Antenna mount – tight and secure	_X_	_	
	Azimuth and stiff arms - tight and secure	_X_	_	
	Antenna covers – good condition	_X_		
	Waveguide hatch – sealed and grounded	_X_		

Note: If any Deviations are found explain in detail in notes section.

Antenna and Tower routine inspection

3. Air Pressure

	Inspect	OK	DEV.	NA			
	Dehydrator Manifold	- installed pr	roperly			-	_X_
	Pressure – correct for	antenna and	system		_		_X_
	Waveguide system -	tight – no air	leaks				_X_
	Pressure alarm switch	nes – installec	and functioning	ng			_X_
	Horn antennas – water	er traps and p	roper pressure		_		_X_
4.	Environment						
	Path obstructions - T	rees, shrubs,	weeds and buil	dings.	_X_		_
	Security - Gates, fend	ces and doors	secure.		_X_		
	General appearance –	Weeds, Tras	h & etc.		_X_	·	
5.	Deviations notes, ex Explain in detail:	ceptions and	recommenda	tions			