

ANTENNA AND TOWER ROUTINE INSPECTION

SITE NAME – Bellingham C.O.

SITE LOCATION – Bellingham, WA.

SITE CLLI – BMLMWA01

DATE – 11/30/2021

INSPECTED BY – Hogue/Ford

ANTENNA AND TOWER ROUTINE INSPECTION

SITE NAME – Friday Harbor

SITE LOCATION – San Juan Island

SITE CLLI - FRHRWAAW

DATE - 12/02/2021

INSPECTED BY – Hogue/Ford

ANTENNA AND TOWER ROUTINE INSPECTION

SITE NAME - Mt. Constitution North Tower

SITE LOCATION - Orcas Island

SITE CLLI - MTCSWAQA

DATE - 12/01/2021

INSPECTED BY - Hogue/Ford

ANTENNA AND TOWER ROUTINE INSPECTION

SITE NAME - Mt. Constitution South Tower

SITE LOCATION - *Orcas Island*

SITE CLLI - MTCSWAQA

DATE – 12/01/2021

INSPECTED BY – Hogue/Ford