

**POST INSPECTION MEMORANDUM**

**Inspector:** Patti Johnson/UTC  
**Reviewed:** Joe Subsits 11/2/2011/UTC  
**Peer Reviewed:** \_\_\_\_\_  
**Follow-Up Enforcement:** No Violation  
**PCP\* PCO\* NOA WL LOC**  
**Director Approval\*** \_\_\_\_\_

**Date:** 10/25/2011

**Operator Inspected:**  
Kelso Beaver Pipeline Company  
Portland General Electric Co.  
3WTC0402  
121 SW Salmon Street  
Portland, OR 97204

**OPID:** 31522

**Region:** Western

**Unit Address:**  
80997 Kallunki Rd  
Clatskanie, OR 97106

**Unit Inspected:** Kelso Beaver Pipeline                      **Company Unit ID:** 9775  
**Unit Type:** Interstate Gas Transmission  
**Inspection Type:** Joint PHMSA/Interstate Agent Operator Qualification Inspection  
**Record Location:** Clatskanie, OR  
**Inspection Dates:** September 26 & 27, 2011  
**AFOD:** 1 ½ days  
**SMART Activity Number:**

**Operator Contact:**  
Kathy Davies, Pipeline Manager  
**Phone:** (503) 464-7300              **Fax:** NA              **Emergency:** (360) 703-0175

**Unit Description:**  
Kelso Beaver Pipeline takes delivery of natural gas from the Williams Northwest Pipeline meter station located east of Kelso, Washington and extends west approximately 18 miles to Columbia County, Oregon. The 20-inch diameter pipeline crosses the Columbia River north of the City of Longview, Washington.

**Facilities Inspected:**  
This inspection covered KB Pipeline in Washington and Oregon.

**Persons Interviewed:**  
Kathy Davies, Pipeline Manager  
Bob Cosentino, Cosentino Consulting

**Probable Violations/Concerns:**

No Probable Violations/Concerns were found.

**Follow up on the history of prior offenses that are still open:**

<b>Prior Offenses (for the past 5 years)</b>		
<b>CPF #</b>	<b>What type of open enforcement action(s)?</b>	<b>Status of the regulations(s) violated (Reoccurrence Offenses, Implement a NOA Revision, Completion of PCO or CO, and etc...)</b>

**Recommendations:**

None.

**Comments:**

No issues found. Team members included Patti Johnson (lead) UTC WA, John Haddow and Tom Finch, PHMSA Western.

**Attachments:**

PHMSA Form 14-OQ Operator Inspection.