From: sendmail@washington-ucc.org

Sent: Tuesday, November 27, 2018 4:19 PM

To: wsdlsafetycommittee@gmail.com

Subject: Complaint Form

Complaint Form Request

Requester Information

Name: Bethel Hart

Company: Bayview Meadows Community Assn.

Company Phone: (281)253-3797 Company Email: bethel@whidbey.com

Company Address: 1986 Bayvista Pl, Freeland, 98249

Ticket Requested: no

Violation Information

Violation RCW: RCW 19.122.030 Violation Section: RCW 19.122.055

Violation Description: The contractor digging the trench for a French drain hit and tried to remove the thrust block

protecting a joint in the community's 6" water main damaging the joint and created a leak.

Violation Address: 1944 Bayvista Pl, Freeland WA 98249

Violation Date: 11/13/18

Alleged Violator

Violator Name: Andrew's LandShapers Violator Phone Number: (360)331-4020

Violator Email: *@whidbey.com

Violator Address: 19123 SR 525, Freeland, 98249

Violator Employess On Site: Andrew

Andrew Damerau

mailto:andrewslandshaping@whidbey.com

Andrew's LandShapers

19123 SR 525 PO Box 216

Freeland, WA 98249

Other Information

Other Information: Andrew was asked to discontinue work on the French drain until the community had resolved the safe distance between a water main and a French drain as well as to request a locate for the water main that runs

Case 18-092


parallel to the French drain. It was observed work was restarted 11/27/18 on the French drain without the community's











Andrew's LandShapers Case 18-092





Case 18-092

Bayview Meadows Comm. Assn vs Andrew's LandShapers



Case 18-092 Andrew's LandShapers



Case 18-092 Andrew's LandShapers



Case 18-092 Andrew's LandShapers

