

**wsdlsafetycommittee@gmail.com**

---

**From:** sendmail@washington-ucc.org  
**Sent:** Wednesday, June 12, 2019 11:48 AM  
**To:** wsdlsafetycommittee@gmail.com  
**Subject:** Complaint Form

## Complaint Form Request

---

### Requester Information

**Name:** Erika Hunter  
**Company:** Puget Sound Energy  
**Company Phone:** (425)456-2854  
**Company Email:** erika.hunter@pse.com  
**Company Address:** PO Box 97034, Bellevue, 98009  
**Ticket Requested:** no

---

### Violation Information

**Violation RCW:** RCW 19.122.030  
**Violation Section:** Excavating without locates; [RCW 19.122.030(2)]  
**Violation Description:** Damage Prevention Rep returned to address and found more work had been done without a locate request, machinery and trucks were on site  
**Violation Address:** 12530 7th Ave NW; Seattle, WA  
**Violation Date:** 04/12/2019

---

### Alleged Violator

**Violator Name:** Vasiliys Construction Plus LLC  
**Violator Phone Number:** (253)333-7820  
**Violator Email:** unknown@unknown.com  
**Violator Address:** 36420 54th ave s, Auburn, 98001  
**Violator Employess On Site:** n/a

---

### Other Information

**Other Information:**

**wsdlsafetycommittee@gmail.com**

---

**From:** sendmail@washington-ucc.org  
**Sent:** Wednesday, June 12, 2019 11:53 AM  
**To:** wsdlsafetycommittee@gmail.com  
**Subject:** Complaint Form

## Complaint Form Request

---

### Requester Information

**Name:** Erika Hunter  
**Company:** Puget Sound Energy  
**Company Phone:** (425)456-2854  
**Company Email:** erika.hunter@pse.com  
**Company Address:** PO Box 97034, Bellevue, 98009  
**Ticket Requested:** no

---

### Violation Information

**Violation RCW:** RCW 19.122.030  
**Violation Section:** Excavating without locates; [RCW 19.122.030(2)]  
**Violation Description:** Damage Prevention Rep returned to address again and found Vasiliys actively digging and trucks on site, no locate ticket called in for this address.  
**Violation Address:** 12530 7th Ave NW; Seattle, WA  
**Violation Date:** 04/15/2019

---

### Alleged Violator

**Violator Name:** Vasiliys Construction Plus LLC  
**Violator Phone Number:** (253)333-7820  
**Violator Email:** unknown@unknown.com  
**Violator Address:** 36420 54TH AVE S, AUBURN, 98001  
**Violator Employess On Site:** Vasiliy

---

### Other Information

**Other Information:**

**wsdlsafetycommittee@gmail.com**

---

**From:** sendmail@washington-ucc.org  
**Sent:** Wednesday, June 12, 2019 11:58 AM  
**To:** wsdlsafetycommittee@gmail.com  
**Subject:** Complaint Form

## Complaint Form Request

---

### Requester Information

**Name:** Erika Hunter  
**Company:** Puget Sound Energy  
**Company Phone:** (425)456-2854  
**Company Email:** erika.hunter@pse.com  
**Company Address:** PO Box 97034, Bellevue, 98009  
**Ticket Requested:** yes  
**Ticket Number:** 19174816  
**Ticket Date:** 05/01/2019

---

### Violation Information

**Violation RCW:** RCW 19.122.030  
**Violation Section:** Excavating without locates; [RCW 19.122.030(2)]  
**Violation Description:** Contract locator arrived to complete the locate at address and found Vasiliys already working. Locator informed Vasiliys that the locate wasn't valid until 5/4/19.  
**Violation Address:** 18820 116th Ave SE, Renton, WA  
**Violation Date:** 05/02/0219

---

### Alleged Violator

**Violator Name:** Vasiliys Construction Plus LLC  
**Violator Phone Number:** (253)333-7820  
**Violator Email:** unknown@unknown.com  
**Violator Address:** 36420 54TH AVE S, Auburn, 98001  
**Violator Employess On Site:** Vasiliy Polivoda

---

### Other Information

# Washington One Call

**Ticket No:** 19158068  
2 FULL BUSINESS DAYS  
**Original Call Date:** 04/23/19 11:01 am  
**Work to Begin Date:** 04/26/19 12:00 am  
**Expiration Date:** 06/07/19 11:15 am

## CALLER INFORMATION

**Company Name:** BACH DRILLING  
**Contact Name:** JEREMY BACH  
**Phone:** 509-899-7777  
**Alt. Contact:** JEREMY BACH  
**Phone:** 509-925-6320

**Fax Phone:**  
**Caller Address:** 3340 WILSON CREEK ROAD ELLENSBURG, WA 98926  
**Email Address:** jeremy@bachdrilling.com

## DIG SITE INFORMATION

**Type of Work:** DRILLING WELL  
**Work Being Done For:** SUSAN TEEM

## DIG SITE LOCATION

**State:** WA  
**County:** KITTITAS  
**Place:** CLE ELUM  
**Address:** 1003  
**Street:** BIG CREEK RD  
**Intersecting Street:** NELSON SIDING RD  
**Location of Work:** EXCAVATION SITE IS ON THE N SIDE OF THE ROAD. ADD IS APX 3/4MI FROM ABV INTER  
AREA MARKED IN PINK  
MARK AREA LOCATED APX 150FT N OF GARAGE AT ABV ADD  
**Remarks:** READ THE AREA MARKED IN WHITE STATEMENT  
**Map Coord NW Lat:** 47.2057289  
**Lon:** -121.1073083  
**SE Lat:** 47.1993041  
**Lon:** -121.1012891

## MEMBERS NOTIFIED


District	Company Name	Marking Concerns	Customer Service	Repair	Status
KITPW01	KITTITAS COUNTY PUBLIC WORKS	509-962-7523	509-962-7523	509-925-4466	Does not report



District	Company Name	Marking Concerns	Customer Service	Repair	Status
PUGE05	PUGET SOUND ENERGY ELECTRIC	888-728-9343	888-225-5773	888-225-5773	Marked, Complete
PUGG05	PUGET SOUND ENERGY GAS	888-728-9343	888-225-5773	888-225-5773	Clear, No Utility Owned Facility in Excavation Area
QLNWA19		800-778-9140	800-283-4237	800-573-1311	Not yet responded
SPCTV01	BLUESPAN	520-207-0549	520-207-0549	520-207-0529	Does not report

Legend:  Locate Polygon

Lat/Lon



Google

100 m

[Report a map error](#)

**wsdlsafetycommittee@gmail.com**

---

**From:** sendmail@washington-ucc.org  
**Sent:** Wednesday, June 12, 2019 12:03 PM  
**To:** wsdlsafetycommittee@gmail.com  
**Subject:** Complaint Form

## Complaint Form Request

---

### Requester Information

**Name:** Erika Hunter  
**Company:** Puget Sound Energy  
**Company Phone:** (425)456-2854  
**Company Email:** erika.hunter@pse.com  
**Company Address:** PO Box 97034, Bellevue, 98009  
**Ticket Requested:** yes  
**Ticket Number:** 19174816  
**Ticket Date:** 05/01/2019

---

### Violation Information

**Violation RCW:** RCW 19.122.030  
**Violation Section:** Excavating without locates; [RCW 19.122.030(5)]  
**Violation Description:** Damage prevention Rep Bob Douglas arrived at address and found Vasiliys digging early and told him he was not legal to dig yet. Vasiliys replied that he had it located previously and knew where things were. A ticket history of the address back to 5/11/18 shows no other locates at this address by this excavator.  
**Violation Address:** 18820 116th Ave SE, Renton, WA  
**Violation Date:** 05/03/2019

---

### Alleged Violator

**Violator Name:** Vasiliys Construction Plus LLC  
**Violator Phone Number:** (253)333-7820  
**Violator Email:** unknown@unknown.com  
**Violator Address:** 36420 54TH AVE S, Auburn, 98001  
**Violator Employess On Site:** Vasiliy Polivoda

---

### Other Information

## PSE Complaint Cases 19-051 through 19-054

**Date:** 05/29/2019

**Requestor:**

Erika Hunter  
Damage Prevention Program Manager  
Puget Sound Energy  
PO Box 97034, EST-4  
Bellevue, WA 98009-9734

**Alleged Violator:**

Vasiliys Construction Plus LLC  
Vasiliy Polivoda  
36420 54TH AVE S  
AUBURN, WA 98001  
WA UBI: 603 122 383  
253-333-7820

**Date:** 05/03/2019

**Damage Prevention Representatives:** Jackson Bergland and Bob Douglas

**Violation(s):**

**Complaint #1:** (04/13/2019) 12530 7th Ave NW; Seattle, WA

- Excavating without locates; [RCW 19.122.030(2)]

**Complaint #2:** (04/15/2019) 12530 7th Ave NW; Seattle, WA

- Excavating without locates; [RCW 19.122.030(2)]

**Complaint #3:** (05/03/2019) 18820 116th Ave SE, Renton, WA

- Excavating without locates; [RCW 19.122.030(2)]

**Complaint #4:** (05/03/2019) 18820 116th Ave SE, Renton, WA

- Excavating without locates; [RCW 19.122.030(5)]


**History Summation:**

Vasiliys Construction LLC has been found working without locates by more than one of our PSE Damage Prevention Reps. Multiple efforts have been made by the DPR to educate them about the importance of complying with RCW 19.122 at every job site location. They have continued to be inconsistent in their compliance with the dig law while excavating. Our representatives have explained the safety hazards to the operator on each of these occasions. Vasiliys Construction LLC has not made adequate efforts to change their business practices to be compliant and work safely. They do have a history of calling in for locates, but are lax on the consistent practice. Their field employees have continued to work without valid locate tickets or before the ticket is valid. The violations have occurred in different developments in different cities.

**Complaint #1:** (04/12/2019) 12530 7th Ave NW; Seattle, WA

- **Ticket Number:** No locate request called in.
- **Original Call Date:** N/A
- **04/09/2018:** Damage Prevention Rep Jackson Bergland was onsite for a damage, insufficient information as to who caused the damage; no locate ticket was issued for this address
- **04/12/2019:** Damage Prevention Rep returned to address and found more work had been done without a locate request, machinery and trucks were on site
- **Damage Prevention Representatives further actions:** Jackson Bergland taped a dig law book to the excavator and took pictures of the work area.
  - **Documented the site through pictures:**
    - Two pictures of machinery onsite in the demo area
    - Picture of dig law book taped to excavator
    - Picture of company truck and license plate.

Picture shows date stamp of 4/12/019





Two pictures of machinery onsite in the demo area:





Picture of dig law book taped to excavator:



Picture of company truck and license plate.:






**Complaint #2:** (04/15/2019) 12530 7th Ave NW; Seattle, WA

- **Ticket Number:** No locate request called in.
- **Original Call Date:** N/A
- **04/15/2019:** Damage Prevention Rep returned to address again and found Vasiliys actively digging and trucks on site, no locate ticket called in for this address.
- **Damage Prevention Representatives further actions:** Jackson Bergland took pictures of the work area and contractor actively working.
  - **Documented the site through pictures:**
    - Five pictures of Contractor in and out of excavator working onsite
    - Picture of company truck

Picture with time date stamp showing when picture was taken:





Pictures of active excavation:
















Picture of company truck:

**Complaint #3 & #4:** (05/03/2019) 18820 116th Ave SE, Renton, WA

- **Ticket Number:** 19174816
- **Original Call Date:** 5/1/19
- **05/02/2019:** Contract locator arrived to complete the locate at address and found Vasiliys already working. Locator informed Vasiliys that the locate wasn't valid until 5/4/19.
- **05/03/2019:** Damage prevention Rep Bob Douglas arrived at address and found Vasiliys digging early and told him he was not legal to dig yet. Vasiliys replied that he had it located previously and knew where things were. A ticket history of the address back to 5/11/18 shows no other locates at this address by this excavator.
- **Damage Prevention Representatives further actions:** Bob Douglas took pictures of the work area and contractor actively working.
  - **Documented the site through pictures:**
    - Date stamped picture provides evidence contractor did not wait until ticket was valid to dig
    - Three pictures of active digging within white marks and within feet of main in right of way

- Picture of company truck
- History of tickets called for this address as evidence that contractor did not have the work area located before this ticket.

Picture with time date stamp showing when picture was taken:





Three pictures of active digging within white marks and within feet of main in right of way:













Picture of company trucks



**Ticket history from 5/11/19:**

1 - 4 of 4 Results  
Go to Record #:

Ticket #	Type	Call Date	Excavator Company	Addr	Street	City
<a href="#">18424403</a>	Phone	09/26/18 13:50:40	JAMES A GUESS, INC	18820	116TH AVE SE	RENTON
<a href="#">19093869</a>	Phone	03/18/19 14:37:43	HOMEOWNER	18820	116TH AVE SE	RENTON
<a href="#">19174816</a>	Phone	05/01/19 15:35:44	VASILY'S CONSTRUCTION PLUS LLC	18820	116TH AVE SE	RENTON
<a href="#">19175919</a>	ITIC	05/02/19 08:55:54	INFRA SOURCE	18820	116TH AVE SE	RENTON

1 - 4 of 4 Results  
Go to Record #: