wsdlsafetycommittee@gmail.com

From: sendmail@washington-ucc.org
Sent: Tuesday, June 8, 2021 10:10 AM
To: wsdlsafetycommittee@gmail.com

Subject: Complaint Form

Complaint Form Request

Requester Information

Name: Kemp Garcia

Company: Linescape of WA Company Phone: (206)920-3722

Company Email: kemp@linescapellc.com

Company Address: PO Box 81243, Seattle, 98108

Ticket Requested: yes Ticket Number: 21244575 Ticket Date: 06/01/21

Violation Information

Violation RCW Code: RCW 19.122.030(3)(a) **Violation Section:** Reasonable Accuracy

Violation Description: A 16" gas line was surface located in the field by PSE's contract locator. During Hydro excavation we did not find the gas line at the locate marks. Linescape ran GPR and found a line that was not located. PSE inspector then toned out the gas line again and found it where the GPR found an unknown line. This was 6 feet from the original

mark

Violation Address: 72nd Ave W & 212th St SW

Violation Date: 06/04/21

Alleged Violator

Violator Name: Puget Sound Energry Violator Phone Number: (000)000-0000 Violator Email: Unknown@PSE.com

Violator Address: Unknown, Bellevue, 98006 Violator Employess On Site: Kemp Garcia

Other Information

Other Information: Definition of Reasonable Accuracy per RCW 19.122.020(23)

6/8/2021 Map Link

Washington One Call

Ticket No: 21244575

2 FULL BUSINESS DAYS

Original Call Date: 06/01/21 10:29 am **Work to Begin Date:** 06/04/21 12:00 am **Expiration Date:** 07/16/21 10:30 am

CALLER INFORMATION

Company Name: LINESCAPE OF WA Type of Excavator: CONTRACTOR Contact Name: KEMP GARCIA **Phone:** 206-920-3722 Alt. Contact: KEMP GARCIA

Phone: 206-920-3722

Fax Phone: 206-299-2899 Caller Address: 6606 URSULA PL S SEATTLE, WA 98108

Email Address: KEMP@LINESCAPELLC.COM

DIG SITE INFORMATION

Type of Work: POTHOLING

Directional Drilling: NO

Type(s) of Excavation Equipment: VACUUM EQUIPMENT

Work Being Done For: GRAHAM CONST

DIG SITE LOCATION

State: WA

County: SNOHOMISH Place: EDMONDS

Address:

Street: 72ND AVE W 212TH ST SW

Intersecting Street: Location of Work: LOCATE FROM NORTH SIDE OF 212TH GOING SOUTH ALONG 72ND AVE W APPROX 300 FT. LOCATE ALL ROW AND UP TO

TEMPORARY FENCE ON WEST SIDE OF ROAD.

Remarks: AREA MARKED IN WHITE PAINT

Map Coord NW Lat: 47.8070565 Lon: -122.3303684

SE Lat: 47.8062973 Lon: -122.3299339

MEMBERS NOTIFIED

District	Company Name	Marking ConcernsCustomer ServiceRepair Status		
CC7721	COMCAST CABLE	800-778-9140	800-934-6489	855-537-6296Marked, Complete
EDMOND(11CITY OF EDMONDS	425-771-0235	425-771-0235	425-771-0235Does not report
GTE01	ZIPLY FIBER	800-778-9140	866-699-4759	866-669-4759Marked, Complete
LYNN01	CITY OF LYNNWOOD	425-754-0741	425-670-6268	425-670-6862Does not report
MCI01	MCI	800-289-3427	800-289-3427	800-289-3427Does not report
PUGG09	PUGET SOUND ENERGY GA	S888-728-9343	888-225-5773	888-225-5773Marked, Utility Representative Required

SNOPUD05 SNOHOMISH PUD #1 ELEC 800-778-9140 425-783-1000 425-783-1000Marked, Complete

Locate Polygon Legend:

Lat/Lon










Case 21-021







Case 21-021 Linscape vs. PSE











Case 21-021 Linscape vs. PSE



Case 21-021 Linscape vs. PSE



Case 21-021 Linscape vs. PSE




Case 21-021 Linscape vs. PSE




Case 21-021 Linscape vs. PSE



Case 21-021



.2Target U2 eta Is




Scale 1:400

Graham

72nd Ave W, 212th St SW, Edmonds

Swath 3/11 Shallow Channel Part 1/1 [0.00ft;31.43ft]



Linescape of WA had called in a locate request on 6/1/21 so that they could start the pothole process. Unfortunately, Linescape could not meet the general Contractor's schedule with a crew in the field. I then called and asked if Bravo Environmental could meet the schedule. They could meet the schedule. They also called in a locate on 6/1/21 so that they could begin digging on 6/4/21. Kemp Garcia from Linescape was still onsite to manage the project.

I received calls from ELM indicating that multiple gas lines in the area were large and high pressure. We knew from the Contractor's plan that there are multiple gas lines in the area.

The gas line located to the furthest east, close to the centerline, was the first line potholed. It was a 16" High-pressure line. Levi White of PSE was at the site when we began digging. Bravo hydro excavated down to a depth of 8 feet and did not find the pipe. During the hydro excavation, Linescape ran a ground-penetrating radar (GPR) locating unit across the area due to a City of Lynnwood Forced Sewer main in the area. We found another strong signature that was just east of the forced sewer during that process but not as far as the located gas line.

When we could not find the gas at the original locate, Levi hooked up his Pipehorn locator and received a signal in the location of the line found during the GPR locate.

We potholed that location and found the 16" gas line. I asked Levi if that size gas line is wrapped in Red. He made a call to another inspector and confirmed that the line would be wrapped in Red. This location was 6 feet away from the paint on the ground. Levi was not onsite when we uncovered the line; however, we did not backfill until he was onsite. Levi did not seem surprised that ELM was off on the locate.

Even with outside dimensions of the 16" line, a person would add 8". The Tolerance zone would then become 32". The marked line would still be out of the tolerance zone by 40".

The reason for this work was so that tiebacks can be designed around the existing utilities and not hit them during construction.

In the Google street view (unknown date), the line appears to be located correctly.

I have also attached the GPR reading showing that we found something close to the forced sewer main and an aerial GPS of the GPR findings. When we ran the GPR, we did not know that the gas line was located in that spot, so we gave it the name of U2 (2nd unknown during scan)