

# WUCC Complaint Form

## Requester Information

---

Your Name:

Julie Metzger

Your Company:

Clallam County PUD

Your Phone Number:

3605653219

Your Email:

jmetzger@clallampud.net

Your Address:

po box 1000

Your City:

carlsborg

Your State:

WA

Your Zip:

98324

Was a locate requested from the call center?  Yes  No

Ticket Number:

23047157

Ticket Date:

02/08/2023

## Violation Information

---

Alleged Violation/Damage:

RCW 19.122.030 Must call for marking two (2) full business days prior to digging.

Other

Section of Law Violated:

don't know

Alleged Violation Date:

02/13/2023

Address of alleged violation:

393 stone rd

City of Alleged Violation:

sequim

State of Alleged Violation:

wa

Zip of Alleged Violation:

98382

Basic Description:

Century Link cleared the dig ticket when they have stuff in the area

## Allleged Violator

---

Company Name:

century link

Company Phone Number:

406-250-9892

Company Email:

john.bemis@lumen.com

Company Address:

Company City:

sequim

Company State:

wa

Company Zip:

98382

Names of Employees on Site:

## Other

---

Additional Information:

look on google map street view and you can see a telephone pedestal in the area that was cleared

By submitting this form I acknowledge that the statements that I alleged are true and accurate to the best of my knowledge.

# My ticket with the bore area highlighted

←

**Ticket information** ⊖

Ticket number: 23047157  
Original Call Date: 02/08/23 02:12 pm  
Work to Begin Date: 02/14/23 09:00 am  
Expiration date: 03/25/23 04:15 pm  
Type/header: 2 FULL BUSINESS DAYS

**Ticket actions** ⊕

**Caller information** ⊖


Company Name: CLALLAM COUNTY PUD  
Type of excavator: UTILITY  
Contact Name: JULIE METZGER  
Phone: 360-565-3219  
Alt Contact: CELL  
Phone: 360-460-8038  
Fax Phone:  
Caller Address: PO BOX 1000 199-1 IDEA PL  
SEQUIM, WA 98382  
Email Address: jmetzger@clallampud.net


**Excavation information** ⊖

↕

The map displays a street layout with Hudson Rd running vertically and Stone Rd running horizontally. An orange rectangular area highlights a section of Stone Rd, indicating the excavation site.

## EXTERNAL: Ticket Check Status for WA Ticket 23047157

 wa@occinc.com  
To Julie Metzger x219

 We removed extra line breaks from this message.

 Rep

CAUTION: Do not click links or attachments unless you recognize the sender and know the content is safe.

Ticket Number: 23047157  
Location: 393 STONE RD SEQUIM, WA

As of 2/14/23 9:00 PST, participating facility owners have responded to Ticket Check as follows:

District Code	Status
CLALLAM COUNTY PUBLIC WKS	Does not report
PUD #1 OF CLALLAM CO	Does not report
CTLQL-CENTURYLINK	Clear, No Utility Owned Facility in Excavation Area
WAVE BROADBAND	Clear, No Utility Owned Facility in Excavation Area

Does not report: This member does not post their positive response status back to this system. It does not mean that they were not notified of the request to excavate. To review this ticket in its entirety, visit Search and Status on [www.managetickets.com](http://www.managetickets.com).

Picture of what is in the field at the location highlighted.

