

WSDL complaint 24-062

Ticket number 24198375

5/23/24

515 W Regina

Narrative: We were boring from the west to the east. We were going to have an exit pit at a power handhole at that point. The house on the north side of the Street, was located as being fed from the west to the east. We stopped the pilot bore approximately 30' away from the exit point to wait for the hydrovac to open up the utilities for us. When we did that we found an electric service that was not located heading west. it was remarked correctly and crossed directly in our bore path. When we opened up the newly marked north crossing the drill head was less than 1' away from hitting it.

View of east exit pit and locates, note 1 secondary electrical line feeding house to the south. Nothing continuing west in the bore path.



location of east exit pit



no secondary power is marked.



East Exit pit

Secondary power is marked coming from the west

We stopped the bore to about 30' short of the east exit pit to wait for the Hydrovac to open it up. When we opened up the exit pit we found 2 secondary power lines. One line appeared to go west.



marked line heading south to the house.


unmarked secondary power line heading west.

new mark coming from the east from the above picture.

locator indicating presence of the drill head on the pilot bore



old mark blacked out



live unmarked power

May 23, 2024 at 11:21:45 AM
509 W Regina Ave
Spokane WA 99218
United States

drill head

unmarked abandoned gas line