
Quality Fence Builders installation of security fence over primary conductor at 6520 S. 228th St. Kent

Search and Status



- Locates were called in 5/24/24 11:01 am
- Work begin date 5/30/24
- Locates paint was put down 6/10, 11 days past the work to begin date.
- White Paint marks cannot be confirmed or denied due to the late nature of the ticket and proceeding weather and landscaping activities.
- ELM documented phone calls to the primary phone number (below).
- The fence company states they have no record of receiving voice mail messages from the tech.

- There is no evidence that the secondary phone number was used by ELM to reach the company.
- PSE has no information that the building owner or fence company reached out to inquire about power structures and easements on the property despite multiple above ground switch gear and concrete vault lids visible.

Quality Fence Builders Contact name: Melissa Applebee

Alt. contact: Kendra Kahne

 Marking instructions: Place: KENT Address: 6520 Street: 228TH ST Intersecting Street: 64TH Location of Work: MARKING INSTRUCTIONS: LOCATE FROM BUILDING ENTRANCE OFF S 228TH ST HEADING WEST TOWARDS 64TH. LOCATE ALONG 64TH AVE S TO NEXT ENTRANCE. DRIVING DIRECTIONS: MCKESSON BUILDING. ENTER OFF 228TH ST

Calls to Quality Fence Builders

5/30 Nothing

5/31 Tech called and left a message with Melissa for extension at 7:28 PM

6/3 Tech called and left a message with Melissa for extension at 4:44 PM

6/4 Tech called and left a message with Melissa for extension at 7:03 PM

6/5 Tech called and left a message with Melissa for extension at 4:24 PM

6/6 Tech called and left a message with Melissa for extension at 6:02 PM

6/7 Nothing

6/10 Completed. 2 Hours 8 minutes 2060 feet of locating.

6/12 Ryan verified from Erika's email that the first date ELM techs were on site was 6/10.



