

---

## REDACTED

---

**From:** Nik Bacher <nbacher@anchorqea.com>

**Sent:** Thursday, April 13, 2023 8:39 AM

**To:** Young, Hunter <young.hunter@epa.gov>; Peterson, Lance <peterstone@cdmsmith.com>

**Cc:** Bob Wyatt <rjw@nwnatural.com>; Patricia Dost <pdost@pearllegalgroup.com>; Ryan Barth <rbarth@anchorqea.com>; Jen Mott <jmott@anchorqea.com>; Joe Smith <jsmith@anchorqea.com>; Billie-Jo Gauley <bgauley@anchorqea.com>; Crystal, Mike <mdcrystal@sevenson.com>

**Subject:** Gasco Sediments Site Additional Depth of Contamination Characterization Investigation Daily Progress Report 04/12/2023

Hunter,

The following is the April 12, 2023, daily progress report for the additional depth of contamination study investigation being conducted at the Gasco Sediments Site Project Area in accordance with the U.S. Environmental Protection Agency (EPA) approved *Revised Additional Depth of Contamination Characterization Addendum within the Gasco Sediment Site Project Area (Addendum)* dated March 23, 2023 (Anchor QEA 2023). This was the thirteenth day of the investigation.

### **Personnel On Site**

- James Melton and Gillian Williams (Anchor QEA, LLC); Rodney LaBrosse, Corben Vega, and Austin Estes (Holt Drilling)
- Oversight: None
- Visitors: None

### **Subsurface Sediment Sampling Program**

- Gravity is preparing a dive plan for EPA review and approval allowing for the retrieval of the drill string left in the sediments at PDI-210.

### **Riverbank Angled Boring Sampling Program**

Angled sonic cores were collected from the following location. All measurements below are as measured along the angled boring trace (i.e., they are not vertical below grade measurements). Measurements will be vertically corrected using AutoCAD at the end of the investigation per the Addendum.

- PDI-217 was advanced at an angle of 20 degrees to a total depth of 50.9 ft below grade and soils were logged from 0 to 50.9 ft below grade. Samples were collected in accordance with the Addendum as follows:
  - Extent of contamination along the angled alignment of the boring (based on visual and olfactory indicators) in PDI-217: 22.3 ft below grade.
  - Samples collected:
    - 20-21, 21-22 ft below grade (archived above visual and olfactory DOC interval)
    - 22-23, 23-24.1, 25-26, 26-26.8, 30-31 ft below grade (selected for analysis, data gaps in intervals selected to reflect recovery in each 5-ft boring advance)
    - 31-32, 32-33 ft below grade (archived)

### **Health and Safety**

- No reportable incidents

### **Samples Shipped**

- No samples were submitted to the lab today.

### **Substantive Discussions with EPA Oversight**

- None

### **Deviations**

- None

### **Niklas Bacher, L.G., P.G.**

Director of Field Services  
Senior Managing Geologist

### **ANCHOR QEA, LLC**

[nbacher@anchorqea.com](mailto:nbacher@anchorqea.com)

949 Market Street, Suite 700

Tacoma, WA 98402

T 206.287.9130

D 206.903.3376

C 206.351.0951

### **ANCHOR QEA, LLC**

Please consider the environment before printing this email.

This electronic message transmission contains information that may be confidential and/or privileged work product prepared in anticipation of litigation. The information is intended for the use of the individual or entity named above. If you are not the intended recipient, please be aware that any disclosure, copying distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at (206) 287-9130.