

Motor Carrier Safety Staff Recommendation

CH

Investigator(s): Alan Dickson

Permit: TE-071219

Assignment No.: 107148

Company name: Stephen Arthur Reeves

Type of assignment:

- Compliance review
- Technical assistance
- Vehicle inspection
- Other: _____

- Education
- Training
- Destination check

Date(s) of activity: 6-28-07

Relevant company history, if any:

Findings: The van had a discharged fire extinguisher; CVSA was issued

Recommended Action:

- No further action.
- Notify the company in writing of the findings by providing a copy of the CR or vehicle inspection report.
- Require the company to submit a compliance plan in response to the 15-day letter requirement or in response to a compliance letter.
- Send the company a compliance letter. Require a response: Yes No
- Issue administrative penalties in the amount of \$
- Issue a complaint.
- Stop company operations.

Recheck: Yes (Date: _____) No

Additional Comments: Mr. Reeves is currently employed as a driver for a major Seattle metro area bus company. He is properly qualified and is knowledgeable of the safety regulations. The safety manual was provided and reviewed during this inspection.

I recommend granting of permanent authority to this applicant.

Investigator's signature: Alan Dickson

Initial Review by: _____ Date: _____

Final recommendation by: K Hunter Date: 7-10-07
CONCERN WITH STAFF RECOMMENDATION TO
WDL. CH/ES AUTHORITY.
Close file. Thanks

Date closed: 7/10/07 By: AK

cc: Alan Dickson
Licensing

2007 MCSAP DATA SHEET

Assignment #:	107148
Date of CR/Inspection:	6-28-07
Carrier Name:	Stephen Arthur Reeves
DBA:	
Permit #:	CH applica, TE-071219
DOT #:	
MC #:	
MotCar #:	

COMPLIANCE REVIEW DATA:

Safety Rating:	
Number of Vehicles Operated:	
Number of Drivers Operated:	
Total Miles for Prior Year:	
Recordable Accidents for Prior Year:	
Accident Ratio:	

PART B VIOLATIONS:

Part 382/Part 40	
Part 383	
Part 387	
Part 390	
Part 391	
Part 392	
Part 395	
Part 396	
Part 397	

cc: *Tom Mc Vaughn*

2007 MCSAP DATA SHEET (cont):

VEHICLE INSPECTION DATA:

Vehicle Type:	MC	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
# of Vehicle Inspections:								1			
# of Defective Vehicles:								1			
Defective Vehicle Ratio:	LEAVE BLANK - RATIO COMPUTER GENERATED										
# of OOS Vehicles:								0			
OOS Vehicle Ratio:	LEAVE BLANK - RATIO COMPUTER GENERATED										
Location of Inspection:	Everett										
Level of Inspection:								5			

VEHICLE INSPECTION VIOLATIONS

Vehicle Type:	MC	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
Brakes											
Steering											
Lights											
Tires/Wheels/Rims											
Horn											
Windshield/Wipers											
Mirrors											
Emergency Equipment/Exits								1			
Coupling Devices											
Frame											
Suspension											
Exhaust											
Other											

Alan Dickson

Inspector(s): _____