

Motor Carrier Safety Staff Recommendation

Upload? Yes No

CA-62946

Permit: TE-071371

Investigator(s): Alan Dickson

Assignment No.: 107172

MOTCAR No.: *M 2 8655*

Company name: Mark Vedmed

Is this company a new entrant? Yes No

Type of assignment:

- Compliance review
- Technical assistance
- Vehicle inspection
- Complaint
- Other: _____

- Education
- Training
- Destination check
- Unannounced CR

Date(s) of activity: 8-2-07

Relevant company history, if any: Applicant held a charter certificate in the past

Findings: One minor lighting defect noted; CVSA sticker was issued

Recommended Action:

- No further action.
- Notify the company in writing of the findings by providing a copy of the CR or vehicle inspection report.
- Require the company to submit a compliance plan in response to the 15-day letter requirement or in response to a compliance letter.
- Send the company a compliance letter. Require a response: Yes No
- Issue administrative penalties in the amount of \$
- Issue a complaint.
- Stop company operations.

Recheck: Yes (Date: _____) No

Is this a high risk carrier?

- Carrier has received a conditional or unsatisfactory safety rating from their last CR.
- Vehicle out-of-service ratio 25% or higher.
- Vehicle defect ratio of 75% or higher.

Additional Comments: Mr. Vedmed is knowledgeable of the safety regulations and is properly qualified. I recommend granting of the permanent charter bus certificate. Add this company to the CH workplan.

Investigator's signature: _____

Initial Review by: _____ Date: _____

Final recommendation by: D Pratt Date: 8/6/07

Agree with staff recommendation. Please
close & file. Thanks

D Pratt

Date closed: 8/2/07 By: CAK

cc: Alan Dickson
Licensing

UNIFORM DRIVER/VEHICLE INSPECTION REPORT

1225086

PERSONNEL NO. J553 DIST / DET

LEVEL: 1 X 2 3 4 5

GENERAL HAZARDOUS MATERIALS

DATE 8.2.07 TIME (MILITARY) BEGUN 14:20 FINISHED 14:45 HAZARD CLASS / DIVISION NO. REPORTABLE QTY? Y N HAZARDOUS WASTE? Y N LOCATION: SR/MP Marysville, Quil Ceda SCALEHOUSE NO. CNTY CODE 31 PLACARD REQUIRED? Y N CARGO TANKS? Y N

CARRIER

CARRIER NAME (Include DBA when applicable) Mark Vedmed DBA: Bellevue Town Car Serv. & CHR

ADDRESS 14548 SE 26th St CH Appliz. TE-DIE

CITY Bellevue STATE WA ZIP CODE 98007 INTERSTATE YES NO DOT NO. ICC NO.

DRIVER

DRIVER NAME Mark Vedmed LICENSE NO. VEDMEM*404L6 STATE WA EXP. YEAR 11

DATE OF BIRTH 6.26.60 MED. CERT. N SHIPPER NAME Empty SHIPPING NO. WAIVER Y N

VEHICLE

REGISTERED OWNER NAME/ADDRESS Carrier G.V.W. 44 PASSENGER PBT RATE

Table with columns: UNIT, TYPE, YEAR/MAKE, CO. UNIT NO., LICENSE NO. / VIN NO., STATE. Row 1: 1, BU, 89 Satra, 2026, B39152C, WA




Table with columns: CFR, VIOLATIONS, D, 1, 2, 3, 4, Unit # O/S, Complied. Row 1: 393.9, Rt Low Beam Headlight Inoperable, X

CVSA DECALS UNIT 1 6569403 UNIT 2 UNIT 3 UNIT 4 NOIC NO.

Vehicle may not be operated until O/S defects noted above are repaired. Driver may not drive until in compliance.

DRIVER SIGNATURE [Signature] OFFICER SIGNATURE [Signature]

2007 MCSAP DATA SHEET

Assignment #:	107172
Date of CR/Inspection:	8-2-07
Carrier Name:	Mark Vedmed
DBA:	Bellevue Towncar and Charters
Permit #:	TE-071371 <i>CH-62946</i>
DOT #:	
MC #:	
MotCar #:	

COMPLIANCE REVIEW DATA:

Safety Rating:	
Number of Vehicles Operated:	
Number of Drivers Operated:	
Total Miles for Prior Year:	
Recordable Accidents for Prior Year:	
Accident Ratio:	

PART B VIOLATIONS:

Part 382/Part 40	
Part 383	
Part 387	
Part 390	
Part 391	
Part 392	
Part 395	
Part 396	
Part 397	

cc: Tom McVangh

2007 MCSAP DATA SHEET (cont):

VEHICLE INSPECTION DATA:

Vehicle Type:	MC	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
# of Vehicle Inspections:	1										
# of Defective Vehicles:	1										
Defective Vehicle Ratio:	LEAVE BLANK - RATIO COMPUTER GENERATED										
# of OOS Vehicles:	0										
OOS Vehicle Ratio:	LEAVE BLANK - RATIO COMPUTER GENERATED										
Location of Inspection:	Marysville										
Level of Inspection:	1										

VEHICLE INSPECTION VIOLATIONS

Vehicle Type:	MC	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
Brakes											
Steering											
Lights	1										
Tires/Wheels /Rims											
Horn											
Windshield/Wipers											
Mirrors											
Emergency Equipment/ Exits											
Coupling Devices											
Frame											
Suspension											
Exhaust											
Other											


Alan Dickson

Inspector(s): _____

Washington State Patrol - UTC
UNIFORM DRIVER/VEHICLE INSPECTION REPORT

1225086

PEISONNEL NO. J553		DIST / DET		LEVEL: 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/>				
GENERAL						HAZARD/DUS MATERIALS		
DATE 8.2.07	TIME (MILITARY) 14:20	FINISHED 14 45	HAZARD CLASS / DIVISION NO.		REPORTABLE QTY? Y	HAZARDOUS WASTE? Y	N	
LOCATION: SH/MP Marysville, Qui Ceda		HOUSE NO. 31	PLACARD REQUIRED? Y	N	CARGO TANKS? Y	N		
CARRIED NAME (include DBA when applicable) Mark Vedmed DBA: Bellevue Town Car Serv. & HTR								
ADDRESS 14548 SE 26th St CH Appliz. TE-0187								
CITY Bellevue	STATE WA	ZIP CODE 98007	INTERSTATE YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	DOT NO.	ICC NO.			
DRIVER								
DRIVER NAME Mark Vedmed		LICENSE NO. VEDMEM * 404L6	STATE WA	EXP. YEAR 11				
DATE OF BIRTH 6/26/00	MED. CERT. <input checked="" type="checkbox"/> N <input type="checkbox"/> WAIVER <input type="checkbox"/> Y <input type="checkbox"/>	SHIPPER NAME Empty		SHIPPING NO.				
VEHICLE								
REGISTERED OWNER NAME/ADDRESS Carrier				G.V.W. 44	PBT RATE PASSENGER			
UNIT	TYPE	YEAR/MAKE	CO. UNIT NO.	LICENSE NO. / VIN NO.	STATE			
1	BU	89 Satra	2026	B39152C	WA			
2								
3								
4								



CFR	VIOLATIONS	D	1	2	3	4	Unit #s OF	Complied
393.9	Rt Low Beam Headlight Inoperable		X					

CVSA DEFECTS UNIT 1 **6569403** UNIT 2 UNIT 3 UNIT 4 NOIC NO.

DRIVER SIGNATURE **[Signature]**

OFFICER SIGNATURE **[Signature]**

--- Vehicle may not be operated until O/S defects noted above are repaired.
 --- Driver may not drive until in compliance.