POST INSPECTION MEMORANDUM

Inspector: Patti Johnson/WUTC Reviewed: Joe Subsits/ WUTC

Follow-Up Enforcement: No Violation

'PCP* PCO* NOA WL LOC Director Approval*

12/18/12

Date: January 4, 2012

Operator Inspected: Gas Transmission Northwest Corporation (GTN)

OPID: 15014

Region: Western

Unit Address (Headquarters):

717 Texas Ave Houston, TX 77002

Unit Inspected: TransCanada's GTN System

RECEIVED

VASH. UT. & TP COMM Unit Address: 201 W North River Dr. Spokane, Suite 505, Spokane, WA 99201

Unit Type: Interstate Gas

Inspection Type: Headquarter Team Operator Qualification Inspection

John Haddow Ross Reineke, PHMSA (Lead)

Patti Johnson, WUTC (Team)

Record Location: Houston, TX

Inspection Dates: March 23 & 24, 2011, PHMSA letters state dates are March 8 & 9, 2011

AFOD: 4

SMART Activity Number: 14 /32.723

Operator Contact: David Dobson

Phone: (832) 320-5667 Fax: NA Emergency: (832) 320-5492

Unit Description:

Trans Canada has a total of 11908 miles of pipeline. 1351 miles are in the Trans Canada Gas

Transmission Northwest System

Facilities Inspected: 15014 Gas Transmission Northwest Corp.

ANR pipeline Co. 405

6660 Great Lakes Gas Transmission Co. 13769 Northern Border Pipeline Co. 30838 Tuscarora Gas Transmission Co.

31145 Portland Natural Gas Transmission System

31891 North Baja Pipeline LLC

Persons Interviewed:

Ken Crowl US Compliance Manager John Chin US Compliance Dan Cerkoney US Compliance Becky Anderson US Compliance Jolene Fifield US Compliance Todd cash from Veriforce

Probable Violations/Concerns:

See PHMSA findings.

Follow up on the history of prior offenses that are still open:

	(Prior Offenses (for the past 5 years)
CPF#	What type of open enforcement action(s)?	Status of the regulations(s) violated (Reoccurrence Offenses, Implement a NOA Revision, Completion of PCO or CO, and etc)

Recommendations:

See PHMSA Reports.

Comments: None

Attachments: None

Version Date: 5/5/08