

**OPERATOR QUALIFICATION
FIELD INSPECTION PROTOCOL FORM**

Inspection Date(s):	June 30, 2010
Name of Operator:	Cascade Natural Gas Corporation
Operator ID (OPID):	31522
Inspection Location(s):	Wenatchee/Moses Lake
Supervisor(s) Contacted:	Sam Grant, GM
# Qualified Employees Observed:	2
# Qualified Contractors Observed:	

Individual Observed	Title/Organization	Phone Number	Email Address
Jason Edson	Service Technician/CNG	509.765.7897	
Clifford Nicholas	Service Technician/CNG	509.765.7897	

To add rows, press TAB with cursor in last cell.

PHMSA/State Representative	Region/State	Email Address
Stephanie Zuehlke	Western/WA	szuehlke@utc.wa.gov

To add rows, press TAB with cursor in last cell.

Remarks:

A table for recording specific tasks performed and the individuals who performed the tasks is on the last page of this form. This form is to be uploaded on to the OQBD for the appropriate operator, then imported into the file.

9.01 Covered Task Performance

Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

9.01 Inspection Results (type an X in exactly one cell below)		Inspection Notes
x	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.02 Qualification Status

Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

9.02 Inspection Results (type an X in exactly one cell below)		Inspection Notes
x	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.03 Abnormal Operating Condition Recognition and Reaction

Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

9.03 Inspection Results (type an X in exactly one cell below)		Inspection Notes
x	No Issue Identified	AOC noted by CNG: cracked aluminum control line. AOC noted by CNG: lockup problems/debris in reg.
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.04 Verification of Qualification

Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

9.04 Inspection Results (type an X in exactly one cell below)		Inspection Notes
<input checked="" type="checkbox"/>	No Issue Identified	
<input type="checkbox"/>	Potential Issue Identified (explain)	
<input type="checkbox"/>	N/A (explain)	
<input type="checkbox"/>	Not Inspected	

9.05 Program Inspection Deficiencies

Have potential issues identified by the headquarters inspection process been corrected at the operational level?

9.05 Inspection Results (type an X in exactly one cell below)		Inspection Notes
<input checked="" type="checkbox"/>	No Issue Identified	
<input type="checkbox"/>	Potential Issue Identified (explain)	
<input type="checkbox"/>	N/A (explain)	
<input type="checkbox"/>	Not Inspected	

Field Inspection Notes

The following table is provided for recording the covered tasks observed and the individuals performing those tasks.

No	Task Name	Name/ID of Individual Observed			Comments
		Jason Edson	Clifford Nicholas		
		Correct Performance (Y/N)	Correct Performance (Y/N)	Correct Performance (Y/N)	
1	Valve Box Maint. V-28		Y		
2	Locating	Y			
3	Reg/Relief Maint/Repair. Reg/Relief Lockup Testing Control line repair		Y		AOC noted by employee: cracked aluminum control line. AOC noted by employee: lockup problems/debris in reg.
4					
5					
6					
7					
8					