OPERATOR QUALIFICATION FIELD INSPECTION PROTOCOL FORM

Inspection Date(s):	December 14, 2011
Name of Operator:	Cascade Natural Gas Co.
Operator ID (OPID):	2128
Inspection Location(s):	Kennewick WA
Supervisor(s) Contacted:	Teresa Esparza, District Manager
# Qualified Employees Observed:	3
# Qualified Contractors Observed:	0

Individual Observed	Title/Organization	Phone Number	Email Address		
Steve Conrad	Tech	509-734-4576	None		
John Bushmaker	Tech	509-734-4576	None		
Dan Hamilton	Corr Tech	509-734-4576	None		

To add rows, press TAB with cursor in last cell.

PHMSA/State Representative	Region/State	Email Address
Scott Rukke	Western/WA	srukke@utc.wa.gov
Dennis Ritter	Western/WA	dritter@utc.wa.gov

To add rows, press TAB with cursor in last cell.

Remarks:

A table for recording specific tasks performed and the individuals who performed the tasks is on the last page of this form. This form is to be uploaded on to the OQBD for the appropriate operator, then imported into the file.

9.01 Covered Task Performance

Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

9.01 Inspection Results (type an X in exactly one cell below)		Inspection Notes	
X	No Issue Identified		
	Potential Issue Identified (explain)		
N/A	N/A (explain)		
	Not Inspected		

9.02 Qualification Status

Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

9.02 Inspection Results (type an X in exactly one cell below)		Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.03 Abnormal Operating Condition Recognition and Reaction

Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

	Inspection Results an X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.04 Verification of Qualification

Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

	Inspection Results an X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.05 Program Inspection Deficiencies

Have potential issues identified by the headquarters inspection process been corrected at the operational level?

	Inspection Results an X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

Field Inspection Notes

The following table is provided for recording the covered tasks observed and the individuals performing those tasks.

		Name/ID of Individual Observed			
		Steve Conrad	John Bushmaker	Dan Hamilton	
		Correct	Correct	Correct	
		Performance	Performance	Performance	· ·
No	Task Name	(Y/N)	(Y/N)	(Y/N)	Comments
1	Relief Valve	Y	Y		Mooneys did not lock up due to temperature. They were removed, cleaned and reassembled and worked properly.
2	Emergency Valve		Y		
3	Reg set point/lockup	Y	Y		
4	CP/Rectifier			Y	
5					
6					
7					
8					

Operations and Maintenance Records Review

If performing an operations and maintenance records review in the course of your inspection, please review a sample of the qualifications of the individuals performing those O&M tasks that are covered under Operator Qualification and check the records for compliance to 192.807 or 195.507.

192.807	Records supporting an individual's current qualifications shall be maintained	Sat.	Unsat.	Not
or	while the individual is performing the covered task. Records of prior			Checked
195.507	qualification and records of individuals no longer performing covered tasks shall			
	be retained for a period of five years.			
		X		

PHMSA (OQ) Field Inspection Form 15 (Rev. 4) May 17, 2007)

Comments:		i	