OPERATOR QUALIFICATION FIELD INSPECTION PROTOCOL FORM

Inspection Date(s):	June 22, 2011
Name of Operator:	Northwest Natural Gas
Operator ID (OPID):	13840
Inspection Location(s):	White Salmon, WA
Supervisor(s) Contacted:	Yurgen (Yogi) Rattay Field Operations & Customer Field Svcs Supv.
# Qualified Employees Observed:	2
# Qualified Contractors Observed:	0

Individual Observed	Title/Organization	Phone Number	Email Address		
Armondo Quintero	Construction 3	503.816.9048	N/A		
Travis Davis	Construction 3	503.816.9048	N/A		

To add rows, press TAB with cursor in last cell.

PHMSA/State Representative	Region/State	Email Address
Stephanie Zuehlke/State Rep	Western/WA	szuehlke@utc.wa.gov

To add rows, press TAB with cursor in last cell.

Remarks:

A table for recording specific tasks performed and the individuals who performed the tasks is on the last page of this form. This form is to be uploaded on to the OQBD for the appropriate operator, then imported into the file.

9.01 Covered Task Performance

Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

	Inspection Results an X in exactly one cell below)	Inspection Notes
Х	No Issue Identified	
	Potential Issue Identified (explain	
	N/A (explain)	
	Not Inspected	

9.02 Qualification Status

Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

1	Inspection Results an X in exactly one cell below)		Inspection Notes	
X	No Issue Identified			
	Potential Issue Identifie	d (explain)		
	N/A (explain)	11 (12 to 12		
	Not Inspected			

9.03 Abnormal Operating Condition Recognition and Reaction

Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

9.03 Inspection Results (type an X in exactly one cell below)		Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.04 Verification of Qualification

Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

9.04 Inspection Results (type an X in exactly one cell below)		Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.05 Program Inspection Deficiencies

Have potential issues identified by the headquarters inspection process been corrected at the operational level?

9.05 Inspection Results (type an X in exactly one cell below)		Inspection Notes	
X	No Issue Identified		
	Potential Issue Identified (explain)		
	N/A (explain)		
	Not Inspected		

Field Inspection Notes

The following table is provided for recording the covered tasks observed and the individuals performing those tasks.

		Na	me/ID of Individual Obs	erved	
4	1 V	Armondo Quintero	Travis Davis		
		Correct Performance	Correct Performance	Correct Performance	
No	Task Name	(Y/N)	(Y/N)	(Y/N)	Comments
1	Locating	Y	Y		Identified AOC's: shallow riser and Atmospheric Corrosion
2	Leak evaluation	Y	. Y		
3					
4					
5					
6					
7					
8					

Operations and Maintenance Records Review

If performing an operations and maintenance records review in the course of your inspection, please review a sample of the qualifications of the individuals performing those O&M tasks that are covered under Operator Qualification and check the records for compliance to 192.807 or 195.507.

192.807 or	Records supporting an individual's current qualifications shall be maintained while the individual is performing the covered task. Records of prior	Sat.	Unsat.	
195.507	qualification and records of individuals no longer performing covered tasks shall			Checked
-	be retained for a period of five years.			
	2008-2011 OQ records reviewed for each			
		х		