

Utility Report Form

Complete and submit this form to your supervisor within 24 hours of any accident

Foreman Name Brendin Harman Supervisor's Name LISA WILLIAMS

Project # _____ Project Name 2190 E SAINT ANDREWS, Shelton WA

Was entire work area walked out prior to job start? Yes No
 Locates verified prior to digging? Yes No Photos prior to digging? Yes No

Person completing report

Date 11-19-19 Print Name LISA WILLIAMS Signature Lisa Williams

Accident Information

Date of hit 11-12-19 Time of hit 11:30 AM Specific Address of hit - Street / City 2190 E. SAINT ANDREWS

Tele _____ Gas _____ Water Power _____ Other _____

Utility Company LAKE LIMERICK

Utility Company Representative Name ROGER MILLMAN

Utility Rep phone # 360-426-3581

Equipment/Machine responsible HOIE HOG/PNEUMATIC MOLE Operator of Equipment/Machine BRENDIN HARMAN

Was anybody injured? Yes No

Describe what happened.

During the hole hog bore across E Saint Andrews the crew struck mislocated water in road. The crew excavated past the area the water was located prior to boring. Water was located in grade 1 shoulder but was 8 to 10' off locate under roadway

Was another contractor involved? Yes No

Name, Address & Phone of contractor _____

Name of Locate Companies LAKE LIMERICK

Locate ticket # 19490445 Date of locates 11/16/19

Was the Utility properly located? Yes No

Depth of Utility Approx 3' to 3 1/2'

Distance of locate from Damaged line 5' to 7' - under asphalt


Utility was notified of service disrupt:
 Date 11-12-19 Time 11:30
11-13-19 10
?

Date and Time utility arrived to repair line: _____
 Number of Utility employees required to repair line? _____

Describe the work performed by the utility to repair the line including equipment and man hours*
Unknown - LAKE Limerick took care of repair

*Include the scope of SEFNCO involvement in all repair work


Date: 11-13-19 Print Name: LISA WILLIAMS Signature: Lisa Williams



E. Saint Andrews 8'-10' {

Struck mislocated Main

H2O Location →



Crews evacuation and begin base.







Lisa Williams <lisa@rainiervalleyinc.com>

Ticket: 19490445

1 message

wa@occinc.com <wa@occinc.com>
To: LISA@rainiervalleyinc.com

Wed, Nov 6, 2019 at 6:33 PM

WASHINGTON UTILITY NOTIFICATION CENTER

DO NOT REPLY TO THIS EMAIL

This ticket is valid for 45 days from the legal start date and time. The expiration date and time is 12/21/2019 6:30 PM .

Washington Ticket#:	19490445	2 FULL BUSINESS DAYS	
Transmit Date:	11/06/19	Time:	6:33 PM
Original Call Date:	11/06/19	Time:	6:29 PM
Work to Begin Date:	11/09/19	Time:	12:00 AM
			Type: WEB

Caller Information

Company:	RAINIER VALLEY CONSTRUCTION	Type:	CONTRACTOR
Contact Name:	LISA WILLIAMS	Phone:	(360) 791-3957
Alt. Contact:	LISA	Phone:	(360) 791-3957
Best Time:		Fax:	(360) 446-7641
Address:	PO BOX 550 PO BOX 550; RAINIER, WA 98576		
Caller Email:	LISA@RAINIERVERALLEYINC.COM		

Dig Site Information

Type of Work: INSTALL CATV SERVICE
Work Being Done For: COMCAST

Dig Site Location

County:	MASON	State:	WA
Place:	SHELTON		
Address / Street:	2190 E SAINT ANDREWS DR		
Nearest Intersection:	E MASON LAKE RD		

Location of Work:

ADDRESS NW OF CROSS STREET ON SOUTH SIDE OF ROAD
FROM EAST SIDE OF HOUSE LOCATE GOING APPROX 200FT TO SAINT ANDREW THEN GO EAST ON BOTH SIDES OF
ROAD APPROX 40FT TO POLE ON NORTH SIDE OF ROAD

Remarks:

AREA MARKED IN WHITE

Map Twp: 21N **Rng:** 3W **Sect-Qtr:** 27-NE,26-NW,23-SW,22-SE
Excavation Coordinates for # Polygons: 1
Poly 1: NW Lat: 47.2918030 **Lon:** -123.0417121 **SE Lat:** 47.2880916 **Lon:** -123.0305970

Members Notified

District	Company	Marking Concerns	Customer Service	Repair
CC7711	COMCAST CABLE	(800)762-0592	(800)934-6489	(855)537-6296
CNG05	CASCADE NATURAL GAS - ABERDEEN	(360)532-2541	(888)522-1130	(888)522-1130

LKLIMK01	LAKE LIMERICK WATER SYSTEM	(360)507-6258	(360)426-3581	(360)507-6258
MPUD301	MASON COUNTY PUD#3	(360)829-5166	(360)426-8255	(360)432-1533
QLNWA16	CTLQL-CENTURYLINK	(800)778-9140	(800)283-4237	(800)573-1311

Excavator Responsibilities

* Please click on the following link to verify and confirm that the area covered represents the correct and complete work site area.

[Link To Map for C_EMAIL](#)

* If the area covered is incomplete or inaccurate, it is your responsibility to notify the center immediately to update and correct the locate. Failure to do so could result in a delay or an incomplete utility locate.

* Any other utilities or notification centers not listed, you will need to contact separately.