

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
58177707	N/A 20FT FUSO
DATE 4/6/2022	

MOTOR CARRIER OPERATOR PMC Moving	INSPECTOR'S NAME (PRINT OR TYPE) David Cram
ADDRESS 2100 196th St. SW Suite 110	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE Lynnwood, WA 98036	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER JL6CCH1#47K017778
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) SSR

VEHICLE COMPONENTS INSPECTED

OK			NEEDS REPAIR			REPAIRED DATE			ITEM	OK			NEEDS REPAIR			REPAIRED DATE			ITEM							
1. BRAKE SYSTEM									6. SAFE LOADING									10. TIRES								
✓									a. Service Brakes										a. Tires on any steering axle of a power unit.							
✓									b. Parking Brake System										b. All other tires.							
✓									c. Brake Drums or Rotors	✓									c. Installation of speed-restricted tires unless specifically designated by motor carrier.							
✓									d. Brake Hose																	
✓									e. Brake Tubing																	
N/A									f. Low Pressure Warning Device	✓																
									g. Tractor Protection Valve																	
									h. Air Compressor																	
									i. Electric Brakes	N/A																
									j. Hydraulic Brakes																	
									k. Vacuum Systems																	
									l. Antilock Brake System																	
									m. Automatic Brake Adjusters	✓																
2. COUPLING DEVICES									7. STEERING MECHANISM									11. WHEELS AND RIMS								
									a. Fifth Wheels										a. Lock or Side Ring							
									b. Pintle Hooks										b. Wheels and Rims							
									c. Drawbar/Towbar Eye										c. Fasteners							
									d. Drawbar/Towbar Tongue										d. Welds							
									e. Safety Devices																	
									f. Saddle-Mounts																	
3. EXHAUST SYSTEM									8. SUSPENSION									12. WINDSHIELD GLAZING								
									a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.										Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).							
									b. Bus exhaust system leaking or discharging in violation of standard.																	
									c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.																	
4. FUEL SYSTEM									9. FRAME									13. WINDSHIELD WIPERS								
									a. Visible leak.										Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.							
									b. Fuel tank filler cap missing.																	
									c. Fuel tank securely attached.																	
5. LIGHTING DEVICES									14. MOTORCOACH SEATS									15. OTHER								
									All lighting devices and reflectors required by Part 393 shall be operable.										Any passenger seat that is not securely fastened to the vehicle structure.							
																			List any other condition(s) which may prevent safe operation of this vehicle.							

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.