

Operator Information Needed for IOCS Database

Date of Inspection: Start Date: March 23, 2009 End Date: March 25, 2009

Number of Inspection Days: 3 **Name of Inspector(s):** Kuang Chu, Washington UTC

Activity Type: I01, Unit inspection, I08-OQ Field Verification

Activity Types: I01 Unit Inspection, I02 Construction Inspection, I03 Failure Investigation, I04 Public Complaint Investigation, I05 Specialized Inspection, I07 Liquid IMP-Field Verification (See Guidance Attached).

Operator ID: 31522 **Operator Name:** Kelso/Beaver Pipeline, C/O Cascade Natural Gas

Unit ID: 9775 **Unit Name:** KB Pipeline

Unit Address: 1332 Vandercook Way, Longview, WA 98362

City: Longview **State:** WA **Zip Code:** 98362

Line Segment(s) Inspected: All areas within WA from Williams' Gate station to rectifier at Eufaula Road

Contact Name: Sam Hicks

Contact Title: Compliance Tech.

Contact Phone: 206-381-6725 **Contact Fax:** _____

Comments: N/A

Probable Violations: YES ____ NO X

If Probable Violations were found provide the following information regarding the compliance correspondence to be sent:

Name of Company Executive: Mike Gardner

Executive Title: Vice President, Operations

Executive Address: 222 Fairview Ave N

City: Seattle **State:** WA **Zip Code:** 98109

Executive Phone: (206) 381-6821

Revised June 14, 2001 - RZB